Kansas City Hyatt Regency Hotel Walkway Collapse

What caused the worst structural engineering disaster in the United States?

The hotel was designed and built with an atrium lobby with walkways above the lobby floor. The critical walkways were the  $4^{th}$  floor walkway, which was directly above the  $2^{nd}$  floor walkway. On July 17, 1981 at 7:05 PM the  $4^{th}$  floor walkway failed and collapsed onto the  $2^{nd}$  floor walkway. At the time there were 1,600 people in the atrium attending a tea dance completion. The collapse caused the death to 114 people.

The original design called for the 4<sup>th</sup> floor walkway and 2nd floor walkway to be hung from the atrium roof by single continuous steel rods that served as the hangers for the walkway supports to the beams under the walkway.

During the structural design review process, the single continuous steel rods got changed to steel rods, going from the atrium roof to the  $4^{th}$  floor beams, and then a second set of rods going from the  $4^{th}$  floor beams to the  $2^{nd}$  floor beams. This structural change effectively doubled the load on the connection at the  $4^{th}$  floor box beam holding up the  $4^{th}$  floor walkway. The  $4^{th}$  floor walkway collapsed over the  $2^{nd}$  floor walkway and they both continued to fall to the atrium floor.

Who is to blame for this engineering tragedy? The courts determined that the structural design engineers were liable for neglecting to properly review the structural shop drawings and allowing changes to occur.